#34123 HeiQ Eco Dry (apparel):



It is the manufacturer's / brand's responsibility to fulfill the local labeling requirements and ensure that the correct hangtag is being attached to their product!

QV = Quality Validation / QC = Quality Control, Washes acc. to. ISO 6330 (suggested 4G)